		L	#	Hits	Search Text	DBs	Time Stamp
7	1	L1		9419	((427/8,9,10,142,404,405,419. 2,524) or (204/192 15 192 6)) CCLS	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46
	2	L2		51431	Eddy adj current		2007/05/04 16:46
	3	L3		143	".mu.m") with (oxide oxidat\$5	USPAT;	2007/05/04 16:51
	4	L4		317	height microns micrometer ".mu." ".mu.m") with (oxide	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46
	5	<b>L</b> 5		3523	L2 with (turbine rotor blade vane superalloy carbide near2	EDO TDO	2007/05/04 16:46
	6	L6		5231	L2 same (turbine rotor blade vane superalloy carbide near2	EDO. TDO.	2007/05/04 16:46
	7	L7		3	L3 same L5	1H:DO1DO -	2007/05/04 16:46

	L #	Hits	Search Text	DBs	Time Stamp
8	L8	12	(L3 and L5) not L7	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46
9	L9	1	(L3 same L6) not (L7 or L8)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04
10	L10	4	(L4 same L5) not (L7 or L8 or	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46
11	L11	5	(L4 same L6) not (L7 or L8 or	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04
12	L12	10	(L4 and L6) not (L7 or L8 or	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46
13	L13	l .	((L3 or L5) and L1) not (L7 or L8 or L9 or L10 or L11 or	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46
14	L14		((L4 or L6) and L1) not (L7 or L8 or L9 or L10 or L11 or L12 or L13)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:46

3/

		L #	Hits	Search Text	DBs	Time Stamp
	15	L15	6	(L3 and (turbine rotor blade vane superalloy carbide near2 alloy)) not (L7 or L8 or L9 or L10 or L11 or L12 or L13 or L14)	USPAT; EPO; JPO;	2007/05/04 16:46
	16	L16	24	or Liu or Lii or Liz or Lis	TICDAT.	2007/05/04 16:46
	17	L17	0	(L4 same (cast casting mold molding)) not (L7 or L8 or L9 or L10 or L11 or L12 or L13 or L14 or L15 or L16)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:48
	18	L18	99	molding) and turbine and repair\$7) not (L7 or L8 or L9 or L10 or L11 or L12 or L13		2007/05/04 16:50
	19	L19 (	\ \( \)	".mu." ".mu.m") with (oxide oxidat\$5 oxidiz\$7 corrod\$5	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:53
	20	L20	42	height microns micrometer ".mu." ".mu.m") with (oxide oxidat\$5 oxidiz\$7 corrod\$5	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:54
	21	L21	42	L20 and (gas adj turbine)	14'D() • . 1 D() • 1	2007/05/04 16:55
•			123			
			Lau			

4B1
-----

	L #	Hits	Search Text	DBs	Time Stamp
22	L22(	0	L21 and (superalloy MCrAlY)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:56
23	L23	ロン	L21 and (Ni nickel Co cobalt) Carbide near2 alloy)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:57
24	L24 (	37 37	L23 and (frequency HF LF)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:58
25	L25	0	L24 not L23	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:59
26	L26/	5	L23 not L24	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:59

L28 G) L18 not L20

B2
----

	L #	Hits	Search Text	DBs	Time Stamp
22	L22	0	L21 and (superalloy MCrAlY)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:08
23	L23	42	L21 and (Ni nickel Co cobalt	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:09
24	L25	0	L24 not L23	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 16:59
25	L24	37	L23 and (frequency HF LF)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:10
26	L26	5	L23 not L24 .	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:05
27	L27	37	L21 and (Ni nickel "Co.m/c."  cobalt Carbide near2 alloy)	16'D(10 . 1D(10	2007/05/04 17:09
28	L28	57	L18 not L20	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:08

<del></del>	L #	Hits	Search Text	DBs	Time Stamp
 29	L29	10	L28 and (superalloy MCrAlY)	L'U()	2007/05/04 17:08
30	L30	23	L28 and (Ni nickel "Co.m/c." cobalt Carbide near2 alloy)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:09
31	L31	24	L29 or L30	16'17'1	2007/05/04 17:09
32	L32	19	L31 and (frequency HF LF)		2007/05/04 17:11
33	L33	5	L31 not L32		2007/05/04 17:17
34	L34	43840	depth height microns micrometer ".mu." ".mu.m") same (oxide oxidat\$5 oxidiz\$7	EPO; JPO;	2007/05/04 17:26
35	L35	134 L38	(L2 and L34 and (gas adj turbine))	L' 137 1	2007/05/04 17:27

5/4/2007, EAST Version: 2.1.0.14

	L #	Hits	Search Text	DBs	Time Stamp
36	L36	$\circ$	molding) same (turbine repair\$7)) not (L7 or L8 or L9 or L10 or L11 or L12 or L13 or L16 or	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:30
37	L37(	0	repair\$7Ni nickel "Co.m/c." cobalt Carbide near2 alloy)) not (L7 or L8 or L9 or L10 or	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	l l

5B

		L #	Hits	Search Text	DBs	Time Stamp
	29	L29 (	10)	L28 and (superalloy MCrAlY)	11.11.11.11.11.11.11.11.11.11.11.11.11.	2007/05/04 17:08
	30	T30 (	23)	L28 and (Ni_nickel "Co.m/c." cobalt Carbide near2 alloy)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:09
/	31	L31(	24	L29 or L30	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2007/05/04 17:09
\	32	L32 (	19	L31 and (frequency HF LF)		2007/05/04 17:10
7	33	L33(	5	L31 not L32		2007/05/04 17:10